


# Preliminary Hand- Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date  
3/28/2019 4:00:00 AM to 3/28/2019 5:00:00 AM



## Recent Benzene Detections

Location Category	Reading Date	Concentration
Division B	3/28/2019 04:10:23	0.090 ppm
Division E	3/28/2019 04:53:31	0.390 ppm
	3/28/2019 04:48:19	2.030 ppm
	3/28/2019 04:45:40	2.890 ppm
	3/28/2019 04:41:39	7.540 ppm
	3/28/2019 04:39:57	0.060 ppm
	3/28/2019 04:21:28	2.500 ppm
	3/28/2019 04:18:18	0.310 ppm
	3/28/2019 04:16:55	0.200 ppm
	3/28/2019 04:14:11	6.380 ppm
	3/28/2019 04:14:02	0.190 ppm
	3/28/2019 04:11:59	0.300 ppm
	3/28/2019 04:10:41	8.000 ppm
	3/28/2019 04:06:06	0.300 ppm
	3/28/2019 04:04:16	1.040 ppm
	3/28/2019 04:04:03	0.330 ppm
Impacted Tank Farm	3/28/2019 04:02:57	0.350 ppm
	3/28/2019 04:02:18	0.900 ppm
	3/28/2019 04:41:44	0.170 ppm
	3/28/2019 04:37:02	0.230 ppm
	3/28/2019 04:34:10	0.110 ppm
Industrial Area	3/28/2019 04:31:12	6.350 ppm
	3/28/2019 04:30:39	0.220 ppm
	3/28/2019 04:45:50	1.250 ppm
	3/28/2019 04:25:29	9.850 ppm
	3/28/2019 04:24:56	2.380 ppm
	3/28/2019 04:21:29	1.450 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis.  
It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only